

Big Bore Auto-Fill Valve



Weatherford®
Drilling & Intervention
Services

Project Description


- Designed to minimize surge pressure effects and reduce potential of plugging float equipment with drill cuttings when running casing in close tolerance annuli.
- Features dual flappers with 3 1/4" bore auto-fill tube & 4" full bore flow path after auto-fill tube is sheared with 3 1/2" ball.
- Seat can be field converted to accommodate smaller trip balls.
- Potential savings of hundreds of thousands of dollars in reduced mud losses and improved casing running speeds.
- Aluminum and composite versions under development.
- Designed to meet API RP10F Category III B.

Status


- Aluminum version currently in Lab Testing phase.

2001 Plan


- Aluminum version ready for field testing by 2nd Quarter, 2001.
- Composite version under development.




Running in Hole




Ball Seated



Pressure & Conversion




Converted Float Valve









Weatherford®
Drilling & Intervention
Services

455BB Float Collar







**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.